



Work Order (Bid Form)

AUDITOR: J SUMMERS

615-473-2343

JSUMMERS@UNITED.NET



WORK ORDER INFORMATION

Work Order Name: WO/90009MD2662/1

Work Order Type: Weatherization

Audit Name: 90009MD2662

CLIENT INFORMATION

Client Name:

Address:

Client ID: 90009MD2662

, 37216

Alt. Client ID: DAVIDSON

AGENCY INFORMATION

Agency: Metropolitan Development and Housing Agency

Agency Phone: (615) 252-8500

Address: 701 South Sixth Street
Nashville, TN 37206

Fax: (615) 252-8533

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

SITE BUILT: 1958
LEAD AND ASBESTOES MAY BE PRESENT
PARTIAL FINISHED BASEMENT

Client Name:

Client ID: 90009MD2662

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2662/1

Report Run On: 4/6/2012

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 4

Measures

Measure 1 Seal Ducts

Components

Inspected

Comment DUCT SEALING MEASURES:

- 1.) MASTIC SEAL ALL SUPPLY REGISTERS, BOOTS, AND JOINTS (11)
- 2.) MASTIC SEAL 2 RETURNS SEAL ALL GAPS 20 X 30 / 12 X 12
- 3.) INSTALL FILTER TO EACH RETURN, LEAVE 5 OF EACH SIZE FOR CLIENT.

| # | Material / Labor | Description / Comment | Units | Estimated | | | Actual | | |
|----|------------------|-----------------------|-------|-----------|-----------|-------|--------|-----------|-------|
| | | | | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 | Miscellaneous Su | Duct Sealing | Each | 1 | | | | | |

Other Detail

| | | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 90009MD2662

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2662/1

Report Run On: 4/6/2012

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 4

Measure 2 Infiltration Redctn**Components****Inspected****Comment** INFILTRATION REDUCTION MEASURES:☐

- 1.) CAULK AND SEAL AL WINDOWS, INTERIOR AND EXTERIOR
- 2.) REPLACE BROKEN PANE IN WD3 (APPROX. SIZE 10" X 39")
CONTRACTOR TO VERIFY)
- 3.) REPLACE BROKEN PANE IN WD9 (APPROX. SIZE 10" X 39")
CONTRACTOR TO VERIFY)
- 4.) DS/WS FRONT AND 2 BACK DOORS (EXTERIOR)
- 5.) DS.WS INTERIOR DOOR TO BSMT
- 6.) DS/WS KNEEWALL DOORS IN ATTIC.
- 7.) SEAL PLUMBING PENETRATIONS IN KITCHEN AND BATH.

| # | Material / Labor | Description / Comment | Units | Estimated | | | Actual | | |
|----|------------------|------------------------|-------|-----------|-----------|-------|--------|-----------|-------|
| | | | | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 | Miscellaneous Su | Infiltration Reduction | Each | 1 | | | | | |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total: **Sub Total:** **Field Notes:**

Client Name:

Client ID: 90009MD2662

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2662/1

Report Run On: 4/6/2012

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 4

Measure 3 Install/Replace Heatpump**Components** HS1,AC1**Inspected**

Comment EXTERIOR CONDENSING UNIT IN-OPERABLE, FURNACE UNIT APPEARS TO BE IN WORKING ORDER, BUT WILL NOT OPERATE WITH OUT CONDENSING UNIT, MUST REPLACE CONDENSING UNIT. ALL DUCT WORK IN GOOD WORKING ORDER.

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|---|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Heating Equipme | Heatpump - 4 kBtu/h Existing, Consult Manual J Data | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | Heatpump - 4 kBtu/h Existing, Consult Manual J Data | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 DWH Tank Insulation****Components****Inspected**

Comment 40 Gal Elec.

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|-----------------------|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Hot Water Equip | DHW Tank Insulation | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | DHW Tank Insulation | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 90009MD2662

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2662/1

Report Run On: 4/6/2012

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 4